

Sample Number:	LDS-04-SW-05	
Sampling Location:	LDS-04	
Matrix:	WATER	
Units:	mg/L	
Date Sampled:	3/19/2021	
Parameter	Result	Flag
Diesel Range Organics	0.98	U
Gasoline Range Organics	0.1	U

Sample Number:	LDS-05-SW-06		LDS-05-SW-07	
Sampling Location:	LDS-05		LDS-05	
Matrix:	WATER		WATER	
Units:	mg/L		mg/L	
Date Sampled:	3/20/2021		3/20/2021	
Parameter	Result	Flag	Result	Flag
Diesel Range Organics	0.94	U	0.95	U
Gasoline Range Organics	0.1	U	0.1	U

Sample Number:	LDS-03-SW-03		LDS-03-SW-04	
Sampling Location:	LDS-03		LDS-03	
Matrix:	WATER		WATER	
Units:	mg/L		mg/L	
Date Sampled:	3/19/2021		3/19/2021	
Parameter	Result	Flag	Result	Flag
Diesel Range Organics	1	U	1.1	
Gasoline Range Organics	0.17		0.51	

Sample Number:	LDS-01-SW-01	
Sampling Location:	LDS-01	
Matrix:	WATER	
Units:	mg/L	
Date Sampled:	3/19/2021	
Parameter	Result	Flag
Diesel Range Organics	0.99	U
Gasoline Range Organics	0.1	U

Legend:

- ★ Incident Location
- 💧 Water Sample Locations

Site Features

- Berm
- Boom
- Underflow Dam
- Temporary Retention Pond
- Water Diversion

Coordinate System: WGS 1984 Web Mercator Auxiliary Sphere
 Projection: Mercator Auxiliary Sphere
 Datum: WGS 1984

Source:
 Background: ESRI World Imagery (2021)
 Water Sample Locations: Moible Field Data START (2021)
 Note: U - Indicates that the compound was analyzed for but not detected.

0 500 1,000 2,000 Feet



Prepared for:
 U.S. EPA - Region 8

Contract: 68HE0820D001
 TO/TD: 80-2013-08

Prepared By:
 Tetra Tech
 START V
 1560 Broadway
 Suite 1400
 Denver, CO



**SURFACE WATER RESULT MAP
 (PRELIMINARY)
 LOVELAND I-25 DIESEL SPILL
 LOVELAND
 LARIMER COUNTY, COLORADO**

Date: 3/24/2021