



# ENVIRONMENTAL RESTORATION LLC.

Daily Work Order No. \_\_\_\_\_

U.S. EPA, Region \_\_\_\_\_

## DAILY WORK ORDER

DATE: JULY 16 2021		TASK ORDER: 8-MANI		PAGE 1 OF 1			
WORK SITE NAME: MANILA LODE		MONITOR(S)					
		<div style="display: flex; justify-content: space-between;"> <span>START</span> <span>USCG</span> <span>OTHER:</span> </div>					
LOCATION (CITY, STATE): MONTEZUMA CO		SHIFT 1 2 3	START TIME: 0700		STOP TIME: 1800		
CONTRACTOR: ENVIRONMENTAL RESTORATION LLC		OSC: PAUL PERONARD, MARTY McCOMB		TO COMPLETION DATE TBD			
<b>1. WORK AUTHORIZED</b>		<b>WORK ACCOMPLISHED</b>					
1. Continue assembly of bypass pipe 2. Rework pond in front of adit 3. Harvest rocks for restoration work 4. Begin pile removal and placement		1. Complete 2. Complete for temp diversion 3. Ongoing 4. Started moving rock from top and placing on access road					
WEATHER CONDITIONS ENCOUNTERED:		NICE					
<b>2. NUMBER OF PERSONNEL AUTHORIZED</b>							
1	RESPONSE MANAGER	0	TRUCK DRIVER	1	FOREMAN		
				2-3	OPERATORS		
					OTHER (SPECIFY)		
1	CLEANUP TECH	1	ACCOUNTANT		H&S TECH.		
				0	LABORERS		
<b>3. EQUIPMENT AND EXPENDABLE MATERIALS AUTHORIZED</b>							
ITEM	QTY	USED	NOT USED / OR DOWN	ITEM	QTY	USED	NOT USED / OR DOWN
Dozer	1	1		Compactor	1	1	
Water Trailer	1	1		Portable Toilets/handwash	3		
Front End Loader	1	1					
Pickup Trucks	3	3					
75Klb Exc	1	1					
Mini Exc	1	1					
<b>4. DAILY CHALLENGES AND RESOLUTION</b>							
1. PORTABLE TOILETS REMAIN ELUSIVE. CONTINUING EFFORTS TO FIND A CONTRACTOR WITH AVAILABLE UNITS THAT SERVES AREA							
2. CAT 336 THUMB NEEDS HYDRAULIC LINE REPAIR. VENDOR LOOKING FOR LOCAL MECHANIC							
3. ATTACHING LINER TO ADIT FACE PROBLEMATIC. WORKED WITH OSC TO FIND WORKABLE SOLUTION DURING CONSTRUCTION							
<b>JULY 12 - 18 OPERATIONAL PERIOD GOALS</b>							
MOBILIZE CREW AND EQUIPMENT, BYPASS WATER, CREATE ACCESS, BEGIN GRADING							
SIGNATURE OF OSC				SIGNATURE OF RESPONSE MANAGER			
X				X			