

APPENDIX B

Photographs



Official Photograph No.: 1

Site Name: McCullough Oil Site


Location: Verbena, Chilton County, Alabama

Photographer: Dustin Morin, START

Subject: START collecting samples for HAZCAT

Date: November 8, 2006

TDD No: TNA-05-001-0016



Official Photograph No.: 2

Site Name: McCullough Oil Site

Location: Verbena, Chilton County, Alabama

Photographer: Dustin Morin, START

Subject: START collecting samples for HAZCAT

Date: November 8, 2006

TDD No: TNA-05-001-0016



Official Photograph No.: 3

Site Name: McCullough Oil Site


Location: Verbena, Chilton County, Alabama

Photographer: Dustin Morin, START

Subject: Samples from various locations waiting for HAZCAT

Date: November 8, 2006

TDD No: TNA-05-001-0016



Official Photograph No.: 4

Site Name: McCullough Oil Site

Location: Verbena, Chilton County, Alabama

Photographer: Dustin Morin, START

Subject: HAZCAT table located in staging area

Date: November 9, 2006

TDD No: TNA-05-001-0016



Official Photograph No.: 5

Site Name: McCullough Oil Site


Location: Verbena, Chilton County, Alabama

Photographer: Dustin Morin, START

Subject: Representative HAZCAT of samples

Date: November 9, 2006

TDD No: TNA-05-001-0016



Official Photograph No.: 6

Site Name: McCullough Oil Site

Location: Verbena, Chilton County, Alabama


Photographer: Steve Wolfe, START

Subject: START vacuuming liquid from drums

Date: January 9, 2007*

TDD No: TNA-05-001-0016

(* Date incorrect on camera)



Official Photograph No.: 7

Site Name: McCullough Oil Site

Location: Verbena, Chilton County, Alabama

Photographer: Steve Wolfe, START

Subject: START vacuuming liquid from AST #1

Date: January 9, 2007*

TDD No: TNA-05-001-0016

(* Date incorrect on camera)



Official Photograph No.: 8

Site Name: McCullough Oil Site

Location: Verbena, Chilton County, Alabama

Photographer: Steve Wolfe, START

Subject: Contents of AST #6

Date: January 10, 2007*

TDD No: TNA-05-001-0016

(* Date incorrect on camera)



Official Photograph No.: 9

Site Name: McCullough Oil Site

Location: Verbena, Chilton County, Alabama

Photographer: Steve Wolfe, START

Subject: AST #6 with end cap cut out

Date: January 10, 2007*

TDD No: TNA-05-001-0016

(* Date incorrect on camera)



Official Photograph No.: 10

Site Name: McCullough Oil Site

Location: Verbena, Chilton County, Alabama


Photographer: Steve Wolfe, START

Subject: Emptying drums of sludge material

Date: January 11, 2007*

TDD No: TNA-05-001-0016

(* Date incorrect on camera)



Official Photograph No.: 11

Site Name: McCullough Oil Site

Location: Verbena, Chilton County, Alabama

Photographer: Steve Wolfe, START

Subject: Emptying filters from AST #7

Date: January 15, 2007*

TDD No: TNA-05-001-0016

(* Date incorrect on camera)



Official Photograph No.: 12

Site Name: McCullough Oil Site

Location: Verbena, Chilton County, Alabama

Photographer: Steve Wolfe, START

Subject: Level C cleanout of AST #6

Date: January 16, 2007*

TDD No: TNA-05-001-0016

(* Date incorrect on camera)



Official Photograph No.: 13

Site Name: McCullough Oil Site

Date: January 17, 2007

Location: Verbena, Chilton County, Alabama

TDD No: TNA-05-001-0016

Photographer: Steve Wolfe, START

Subject: Using the nibbler to cut into the side of AST #4



Official Photograph No.: 14

Site Name: McCullough Oil Site

Date: February 17, 2007

Location: Verbena, Chilton County, Alabama

TDD No: TNA-05-001-0016

Photographer: Art Leskovich, START

Subject: Moving the AST to the cutting area



Official Photograph No.: 15

Site Name: McCullough Oil Site

Location: Verbena, Chilton County, Alabama

Photographer: Art Leskovich, START

Subject: Opening the AST

Date: February 17, 2007

TDD No: TNA-05-001-0016



Official Photograph No.: 16

Site Name: McCullough Oil Site

Location: Verbena, Chilton County, Alabama

Photographer: Art Leskovich, START

Subject: Folded ASTs after being opened and compressed

Date: February 17, 2006

TDD No: TNA-05-001-0016



Official Photograph No.: 17

Site Name: McCullough Oil Site

Location: Verbena, Chilton County, Alabama

Photographer: Art Leskovich, START

Subject: Cleaned tank containment area

Date: February 17, 2007

TDD No: TNA-05-001-0016