



DRAWN BY: KYH CHECKED BY: JRN	DATE: 03/24/2008 PROJECT: 070057056	<b>Sample Locations</b> [Red Square with Cross] Surficial Soil Sample [Red Circle with Cross] Soil Boring/Monitoring Well [Red Square with Cross] Test Pit	<b>Other Site Features</b> [Black Outline] Building [Dashed Black Outline] Former Building [Grey Outline] Interior Room [Black Line] Retaining Wall [Black Dotted Line] Drum Storage [Green Line] Storm Drain [Pink Line] Fuel Line [Black Line] Sewer Line	[Black Circle with Cross] DEP Monitoring Well [Grey Circle with Cross] DEP Monitoring Well Not Located [Yellow Circle] Manhole [Grey Square] Test Pit [Grey Square] Catch Basin [Grey Square] Soil Boring [Yellow Circle] UST [Green Circle] AST [White Circle] Former UST
<b>Credere Associates, LLC</b> 222 St. John Street Suite 314 Portland, Maine 04102 Tel. (207) 828-1272 Fax (207) 774-6907		<b>Figure 2 Sample Location Plan</b>	<b>SMRPC—Stenton Trust Mill 13 River Street Sanford, ME</b>	0      55      110 Feet 1 inch equals 65 feet <b>NORTH</b>