

Drum Inventory Table  
Plabell Rubber Manufacturing Plant Site  
Toledo, Lucas County, Ohio  
Drum Inventory Sheet  
September 10-11, 2008

Drum Number	Building	Location in Building	Container/Drum	Type	Size	Condition	Hazcat Drum (pH and/or Flammability) (RESULTS)	Comments
D-1	Bld-1 (330 S St Claire)	De-Flash	Drum/Steel	Close Top	55-gallon	good	Not sampled	Hydraulic Oil/Full
D-2	Bld-1 (330 S St Claire)	De-Flash	Drum/Steel	Close Top	55-gallon	good	Not sampled	Hydraulic Oil/Empty
D-3	Bld-1 (330 S St Claire)	De-Flash	Drum/Steel	Close Top	55-gallon	good	Not sampled	76 Soluble oil (Valvoline) (4505061.03) Partial to Full
D-4	Bld-1 (330 S St Claire)	De-flash	Drum/Steel	Close Top	55-gallon	good	Not sampled	Lube compound (Empty)
D-5	Bld-1 (330 S St Claire)	De-flash	Drum/Steel	Close Top	55-gallon	good	Not sampled	Gear Lube/partially full
D-6	Bld-1 (330 S St Claire)	De-flash	Drum/Steel	Close Top	55-gallon	good	Not sampled	Gear Lube Empty
D-7	Bld-1 (330 S St Claire)	De-flash	Drum/Steel	Close Top	55-gallon	good	Not sampled	Reg LR&O Texaco Partial
D-8	Bld-1 (330 S St Claire)	Inspection/Washing Area	Container/Plastic	Close Top	10-gallon	good	Not sampled	Labeled "Chemsearch" possible manufacturer
D-9	Bld-1 (330 S St Claire)	Inspection/Washing Area	Container/Steel	Open Top	5-gallon	fair	Not sampled	paint supplies
D-10	Bld-1 (330 S St Claire)	Inspection/Washing Area	Container/Steel	Open Top	5-gallon	fair	Yes/flam test – (Positive for FLAM)	Bonding Adhesive Material Hazcatted -Flammable
D-11	Bld-1 (330 S St Claire)	Inspection/Washing Area	Container/Steel	Open Top	5-gallon	Good	Not sampled	Bonding Adhesive (Same as D-10)
D-12	Bld-1 (330 S St Claire)	Inspection/Washing Area	Container/	Open Top	5-gallon	Good	Not sampled	Partially full No ID or labels possible oil material
D-13	Bld-1 (330 S St Claire)	Inspection/Washing Area	Container/Steel	Open Top	5-gallon	fair	Yes/flam test – (Positive for FLAM)	Liquid paint thinner partial Hazcat – Flammable, pH 6-8
D-14	Bld-1 (330 S St Claire)	Inspection/Washing Area	Container/Plastic	Open no lid	5-gallon	fair	Not sampled	Partial with material (paint dried)
D-15	Bld-1 (330 S St Claire)	Inspection/Washing Area	Container	Open no lid	5-gallon	poor	Not sampled	Partially full No ID or labels possible oil material
D-16	Bld-1 (330 S St Claire)	Inspection/Washing Area	Container	Open no lid	5-gallon	poor	Not sampled	Partially full No ID or labels possible oil material

Drum Inventory Table  
 Plabell Rubber Manufacturing Plant Site  
 Toledo, Lucas County, Ohio  
 Drum Inventory Sheet  
 September 10-11, 2008

Drum Number	Building	Location in Building	Container/Drum	Type	Size	Condition	Hazcat Drum (pH and/or Flammability) (RESULTS)	Comments
D-17	Bld-1 (330 S St Claire)	Inspection/Washing Area	Container	Open no lid	5-gallon	poor	Not sampled	Partially full No ID or labels possible oil material
D-18	Bld-1 (330 S St Claire)	Inspection/Washing Area	Container/Steel	Closed top	5-gallon	good	Yes/flam test –(Positive for Flammability)	Liquid material –Flammable, pH 6-8 Marked as “Corrosion Preventer”
Assorted Small containers	Bld-1 (330 S St Claire)	Inspection/Washing Area	Various	Various	1 gallon or less	poor to fair	Not sampled	Paint supplies and other small VOC containers
D-19	Bld-1 (330 S St Claire)	Inspection/Washing Area	Container	Open	5-gallon	Fair	Not sampled	–
Other Containers 1 gal or less	Bld-1 (330 S St Claire)	Inspection/Washing Area	12 Containers		1-gallon	poor	Not sampled	Various types of 1-gallon containers mainly for painting supplies and gas cans (open) 12
D-20	Bld-1 (330 S St Claire)	Room Washing/Dock	Drum/Poly	Closed top	55-gallon	Good	Not sampled	–
D-21	Bld-1 (330 S St Claire)	Room Washing/Dock	Drum/steel	Closed top	55-gallon	Good	Not sampled	–
D-22	Bld-1 (330 S St Claire)	Room Washing/Dock	Drum/poly	Closed Top	30-gallon	good	Not sampled	–
D-23	Bld-1 (330 S St Claire)	Room Washing/Dock	Drum/steel	Closed Top	55-gallon	Fair	Not sampled	1/4 full
D-24	Bld-1 (330 S St Claire)	Room Washing/Dock	Drum/steel	Closed Top	55-gallon	fair	Not sampled	–
D-25	Bld-1 (330 S St Claire)	Room Washing/Dock	Drum/steel	Closed Top	55-gallon	fair	Not sampled	Approx 1/8 full liquid
D-26	Bld-1 (330 S St Claire)	Room Washing/Dock	Drum/steel	Closed Top	55-gallon	Fair	Not sampled	Empty
D-27	Bld-1 (330 S St Claire)	Room Washing/Dock	Drum/steel	Closed Top	55-gallon	Fair	Not sampled	Empty

Drum Inventory Table  
 Plabell Rubber Manufacturing Plant Site  
 Toledo, Lucas County, Ohio  
 Drum Inventory Sheet  
 September 10-11, 2008

Drum Number	Building	Location in Building	Container/Drum	Type	Size	Condition	Hazcat Drum (pH and/or Flammability) (RESULTS)	Comments
D-28	Bld-1 (330 S St Claire)	Room Washing/Dock	Drum/steel	Closed Top	55-gallon	Fair	Not sampled	Empty
Containers in Lab	Bld-1 (330 S St Claire)	Lab Room	Various	Various	1 gal or less	Fair to poor	Not sampled	Various containers marked and unmarked
D-29	Bld-1 (330 S St Claire)	Trim Room	Drum/fiber	open no lid	55-gallon	poor	Not sampled	Garbage material Non-hazardous
D-30	Bld-1 (330 S St Claire)	Trim Room	Drum/fiber	open no lid	55-gallon	poor	Not sampled	Garbage material Non-hazardous
D-31	Bld-1 (330 S St Claire)	Trim Room	Drum/fiber	open no lid	55-gallon	poor	Not sampled	Garbage material Non-hazardous
D-32	Bld-1 (330 S St Claire)	Trim Room	Drum/fiber	open no lid	55-gallon	poor	Not sampled	Garbage material Non-hazardous
D-33	Bld-1 (330 S St Claire)	Trim Room	Drum/fiber	open no lid	55-gallon	poor	Not sampled	Garbage material Non-hazardous
D-34	Bld-1 (330 S St Claire)	Trim Room	Drum/fiber	open no lid	55-gallon	poor	Not sampled	Garbage material Non-hazardous
D-35	Bld-1 (330 S St Claire)	Trim Room	Drum/fiber	open no lid	55-gallon	poor	Not sampled	Garbage material Non-hazardous
D-36	Bld-1 (330 S St Claire)	Trim Room	Drum/Poly	open no lid	55-gallon	poor	Not sampled	Garbage material Non-hazardous
D-37	Bld-1 (330 S St Claire)	Trim Room	Drum/Poly	open no lid	55-gallon	poor	Not sampled	Garbage material Non-hazardous
D-38	Bld-1 (330 S St Claire)	Trim Room	Drum/Poly	open no lid	55-gallon	poor	Not sampled	Garbage material Non-hazardous
D-39	Bld-1 (330 S St Claire)	Trim Room	Container/Steel	Closed top	5-gallon	poor	Not sampled	Garbage material Non-hazardous
D-40	Bld-1 (330 S St Claire)	Trim Room	Cylinder	0.5 L	TBD	good	Not sampled	cylinder (small)
D-41	Bld-1 (330 S St Claire)	Trim Room	Drum/poly	Closed top	55-gallon	good	Not sampled	Blue drum partial to full (Boilerguard is the product name on the label)

Drum Inventory Table  
Plabell Rubber Manufacturing Plant Site  
Toledo, Lucas County, Ohio  
Drum Inventory Sheet  
September 10-11, 2008

Drum Number	Building	Location in Building	Container/Drum	Type	Size	Condition	Hazcat Drum (pH and/or Flammability) (RESULTS)	Comments
D-42	Bld-1 (330 S St Claire)	Trim Room	Container/Fiber	Open Top	3-gallon	poor	Not sampled	1/4 full of powder material
D-43	Bld-1 (330 S St Claire)	Lab Room	Container/Poly	Open Top	5-gallon	fair	Not sampled	1/8 full
D-44	Bld-1 (330 S St Claire)	Lab Room	Container/Poly	Open Top	5-gallon	fair	Not sampled	Diamond Kote
D-45	Bld-1 (330 S St Claire)	Lab Room	Container/Poly	Open Top	5-gallon	fair	Not sampled	
D-46	Bld-1 (330 S St Claire)	Lab Room	Container/Poly	Open Top	5-gallon	fair	Not sampled	Rubber Chem Label
D-47	Bld-1 (330 S St Claire)	Lab Room	Container/Poly	Open Top	5-gallon	fair	Not sampled	Rubber Chem Label
D-48	Bld-1 (330 S St Claire)	Lab Room	Container/Poly	Open Top	5-gallon	fair	Not sampled	Rubber Chem Label
D-49	Bld-1 (330 S St Claire)	Lab Room	Container/Poly	Close Top	2-gallon	good	Not sampled	Dexter Frekote (1-EM)
Lab-1	Bld-1 (330 S St Claire)	Lab Room	Various	Various	1 gal or less	various	Not sampled	Over 350 small containers in the lab area inside the cabinets (7)
D-50	Bld-1 (330 S St Claire)	Boiler Area	Drum/Poly	Open Top	55-gallon	good	Not sampled	Boilerguard 781
D-51	Bld-1 (330 S St Claire)	Boiler Area	Drum/Poly	Open Top	55-gallon	good	Not sampled	Boilerguard 781
D-52	Bld-1 (330 S St Claire)	Boiler Area	Cylinder	Cylinder	30-gallon	poor	Not sampled	water tank cylinder (water softener?)
D-53	Bld-1 (330 S St Claire)	Boiler Area	Cylinder	Cylinder	30-gallon	poor	Not sampled	water tank cylinder (water softener?)
D-54	Bld-1 (330 S St Claire)	Boiler Area	Container/Poly	Storage Tank	35-gallon	poor	Not sampled	Blue storage tank poly
D-55	Bld-1 (330 S St Claire)	Boiler Area	Drum/Poly	Close Top	55-gallon	fair	Not sampled	Blue poly drum
D-56	Bld-1 (330 S St Claire)	Molding Area	Container/Poly	Close Top	5-gallon	fair	Not sampled	Oil Material (<1/2 full)
D-57	Bld-1 (330 S St Claire)	Molding Area	Drum/fiber	Open Top	55-gallon	poor	Not sampled	color powder
D-58	Bld-1 (330 S St Claire)	Molding Area	Drum/fiber	Open Top	55-gallon	Fair/poor	Not sampled	Pellets
D-59	Bld-1 (330 S St Claire)	Molding Area	Trash can/poly	No lid	30-gallon	poor	Not sampled	Partial with material
D-60	Bld-1 (330 S St Claire)	Molding Area	Drum/fiber	No lid	30-gallon	poor	Not sampled	Half full with rubber pellets
D-61	Bld-1 (330 S St Claire)	Molding Area	Trash can/poly	No lid	30-gallon	poor	Not sampled	Powder (white) no labels
D-62 (four similar containers)	Bld-1 (330 S St Claire)	Molding Area	Trash can/poly	No lid	10-gallon	poor	Not sampled	Four Container no lids that contained green liquid. Recycle containers 80% full

Drum Inventory Table  
 Plabell Rubber Manufacturing Plant Site  
 Toledo, Lucas County, Ohio  
 Drum Inventory Sheet  
 September 10-11, 2008

Drum Number	Building	Location in Building	Container/Drum	Type	Size	Condition	Hazcat Drum (pH and/or Flammability) (RESULTS)	Comments
D-63	Bld-1 (330 S St Claire)	Molding Area	Container		1-gallon	poor	Not sampled	Unknown
D-64	Bld-1 (330 S St Claire)	Molding Area	Box/Fiber	NA		poor	Not sampled	Powder (white) no labels
D-65	Bld-1 (330 S St Claire)	Molding Area	Box/Fiber	NA		poor	Not sampled	
D-66	Bld-1 (330 S St Claire)	Molding Area	Drum/fiber	Open Top	30-gallon	poor	Yes (possible flammable had sulfur smell)	Harmful near food label "Copper Dimehtyldithiocarbonate" (Solid powder)
D-67	Bld-1 (330 S St Claire)	Molding Area	Fiber	Open Top	30-gallon	poor	Not sampled	Drum in poor condition. Lid off and the fiber was deteriorating (similar contents as D-66 (potentially))
D-68	Bld-1 (330 S St Claire)	Molding Area	Fiber	Open Top	30-gallon	poor	Not sampled	Drum in poor condition. Lid off and the fiber was deteriorating. Plastic bag inside fiber drum approx 1/2 full
D-69	Bld-1 (330 S St Claire)	Molding Area	Fiber	Open Top	30-gallon	poor	Not sampled	Had "40% Dicumyl Peroxide" label on the container (cas # 80-43-3)
D-70	Bld-1 (330 S St Claire)	Molding Area	Trash can/poly	Open can	20 to 30-gal	fair	Not sampled	Contained pellets/powder
D-71	Bld-1 (330 S St Claire)	Molding Area	Box/Fiber	Open can	21 to 30-gal	fair	Not sampled	Contained pellets/powder
D-72	Bld-1 (330 S St Claire)	Molding Area	Box/Fiber	Open Box	2.5 cubic ft	poor	Not sampled	Disulfur-de-bis(N-Ndimethyl triiocarbmyl CAS 137-26-8 which is TETRAMETHYLTHIURAM DISULFIDE (THIRAM)

Drum Inventory Table  
 Plabell Rubber Manufacturing Plant Site  
 Toledo, Lucas County, Ohio  
 Drum Inventory Sheet  
 September 10-11, 2008

Drum Number	Building	Location in Building	Container/Drum	Type	Size	Condition	Hazcat Drum (pH and/or Flammability) (RESULTS)	Comments
D-73	Bld-1 (330 S St Claire)	Molding Area	Box/Fiber	Open Box	2.5 cubic ft	poor	Not sampled	Disulfur-de-bis(N-Ndimethyl trthiocarbmy...Cas # 137-26-8 which is TETRAMETHYLTHIURAM DISULFIDE (THIRAM)
D-74	Bld-1 (330 S St Claire)	Molding Area	Trash can/poly	Open Top	30 gallon	fair	Not sampled	Contained pellets/powder ion plastic bag inside the drum
D-75	Bld-1 (330 S St Claire)	Molding Area	Drum/fiber	Open Top	30-gallon	poor	Not sampled	Harmful near food label "Copper Dimehtyldithiocarbonate" (Solid powder)
D-76	Bld-1 (330 S St Claire)	Molding Area	Drum/fiber	Open Top	30-gallon	poor	Not sampled	Powder (white) no labels
D-77	Bld-1 (330 S St Claire)	Molding Area	Trash can/poly	Open can	30-gallon	fair	Not sampled	White Pellets
D-78	Bld-1 (330 S St Claire)	Staging Room	Steel Container	Closed top	2-gallon	fair	Not sampled	less than half full
D-79	Bld-1 (330 S St Claire)	Staging Room	Drum/Steel	Closed top	55-gallon	good	Not sampled	1A2 drum with liquid with elevated PID readings over 40 ppm.
D-80	Bld-1 (330 S St Claire)	Staging Room	Steel Container	assorted	2-gallon	fair	Not sampled	Assorted 1 to 2 gallon containers (7)
D-81	FSB	Flammable Stroage Room	Steel Drum	Close Top	55-gallon	fair	Not sampled	
D-82	FSB	Flammable Stroage Room	Steel Drum	Close Top	55-gallon	fair	yes Flammable test Positive pH=6 PID Reading - 977 ppm	Marked as toluene and approximately 10 to 15% full. Labeled "Toluene"
D-83	FSB	Flammable Stroage Room	Steel Drum	Close Top	55-gallon	fair	yes- Flammability test - Neg pH=7 PID reading was 87 ppm	No markings and fulll.

Drum Inventory Table  
Plabell Rubber Manufacturing Plant Site  
Toledo, Lucas County, Ohio  
Drum Inventory Sheet  
September 10-11, 2008

Drum Number	Building	Location in Building	Container/Drum	Type	Size	Condition	Hazcat Drum (pH and/or Flammability) (RESULTS)	Comments
D-84	FSB	Flammable Storage Room	Steel Drum	Close Top	55-gallon	fair	yes Flammable test Positive pH=6 PID Reading - 977 ppm	Drum completely full with clear liquid.
D-85	FSB	Flammable Storage Room	Steel Drum	Close Top	55-gallon	fair	Not sampled	10 to 15% full
D-86	FSB	Flammable Storage Room	Steel Drum	Close Top	55-gallon	fair	Not sampled	Partially full No ID or labels possible oil material
D-87	FSB	Flammable Storage Room	Steel Drum	Close Top	55-gallon	fair	yes, Flammability test Neg pH=6, PID = 189 ppm	Full with Label "MEK"
D-88	FSB	Flammable Storage Room	Poly Container	Close Top	5-gallon	Poor	Not sampled	Marked as flammable
D-89	FSB	Flammable Storage Room	Steel Container	Close Top	5-gallon	Poor	Not sampled	Marked as flammable
D-90	FSB	Flammable Storage Room	Steel Container	Close Top	5-gallon	Poor	Not sampled	Marked as flammable
D-91	FSB	Flammable Storage Room	Steel Container	Close Top	5-gallon	Poor	Not sampled	Marked as flammable
D-92	FSB	Flammable Storage Room	Steel Container	Close Top	5-gallon	Poor	Not sampled	Marked as flammable
D-93	FSB	Flammable Storage Room	Steel Container	Close Top	5-gallon	Poor	Not sampled	Marked as flammable
D-94	FSB	Flammable Storage Room	Steel Container	Close Top	5-gallon	Poor	Yes, Flammability test Neg. pH 4	Possible corrosive material
D-95	FSB	Flammable Storage Room	Poly Container	Close Top	5-gallon	Poor	Not sampled	Marked as flammable
D-96	FSB	Flammable Storage Room	Steel Container	Close Top	5-gallon	Poor	Not sampled	Marked as flammable
D-97	FSB	Flammable Storage Room	Steel Container	Close Top	5-gallon	Poor	Not sampled	Marked as flammable

Drum Inventory Table  
Plabell Rubber Manufacturing Plant Site  
Toledo, Lucas County, Ohio  
Drum Inventory Sheet  
September 10-11, 2008

Drum Number	Building	Location in Building	Container/Drum	Type	Size	Condition	Hazcat Drum (pH and/or Flammability) (RESULTS)	Comments
D-98	FSB	Flammable Storage Room	Steel Container	Close Top	5-gallon	Poor	Not sampled	Marked as flammable
D-99	FSB	Flammable Storage Room	Steel Container	Close Top	5-gallon	Poor	Not sampled	Thixon
D-100	FSB	Flammable Storage Room	Steel Container	Close Top	5-gallon	Poor	Not sampled	Marked as flammable
D-101	FSB	Flammable Storage Room	Steel Container	Close Top	5-gallon	Poor	Not sampled	Marked as flammable
D-102	FSB	Flammable Storage Room	Steel Container	Close Top	5-gallon		Not sampled	Marked as flammable
D-103	FSB	Flammable Storage Room	Steel Container	Close Top	5-gallon		Not sampled	Marked as flammable
D-Various 1 gal or less	FSB	Flammable Storage Room	Steel Container	Close Top	5-gallon		Not sampled	Paint supplies and other small VOC containers
D-Building 2 (228 S. St Claire (6 floors))	Bld-2 (228 S. St Claire)	3 floor	Fiber Drums (6)	Open Top	30 gallon	good	Not sampled	Pallet of similar material as D-66 "Harmful near food label "Copper Dimehtyldithiocarbonate" (Solid powder)" . Pallet seran wrapped full. pallet with fiber drums(6 drums)
D-Building 2 (228 S. St Claire (6 floors))	Bld-2 (228 S. St Claire)	2 floor	Fiber Drum	Open Top	30-gallon	good	Not sampled	Harmful near food label "Copper Dimehtyldithiocarbonate" (Solid powder)
D-104	Bld-3 (227 S. St Claire)	Main Floor	Steel Drum	Close Top	55-gallon	Fair	Not sampled	Oil Material (full)
D-105	Bld-3 (227 S. St Claire)	Main Floor	Steel Container	Open Top	5-gallon	Fair	Not sampled	Oil Material (Partial) no lid.

Drum Inventory Table  
 Plabell Rubber Manufacturing Plant Site  
 Toledo, Lucas County, Ohio  
 Drum Inventory Sheet  
 September 10-11, 2008

Drum Number	Building	Location in Building	Container/Drum	Type	Size	Condition	Hazcat Drum (pH and/or Flammability) (RESULTS)	Comments
D-106	Bld-3 (227 S. St Claire)	Main Floor	Steel Container	Open Top	5-gallon	Fair	Not sampled	Oil Material (Partial)
D-107	Bld-3 (227 S. St Claire)	Main Floor	Poly Container	Close Top	5-gallon	Fair	Not sampled	Oil Material (Partial)
D-108	Bld-3 (227 S. St Claire)	Main Floor	Poly Container	Close Top	5-gallon	Fair	Not sampled	Oil Material (Partial)
D-109	Bld-3 (227 S. St Claire)	Main Floor	Steel Container	Open Top	5-gallon	Fair	Not sampled	Partial
D-110	Bld-3 (227 S. St Claire)	Main Floor	Steel Container	Open Top	5-gallon	Fair	Not sampled	Partial
D-111	Bld-3 (227 S. St Claire)	Main Floor	Steel Container	Open Top	5-gallon	Fair	Not sampled	Partial
D-112	Bld-3 (227 S. St Claire)	Main Floor	Steel Container	Open Top	5-gallon	Fair	Not sampled	Partial
D-113	Bld-3 (227 S. St Claire)	Main Floor	Steel Container	Open Top	5-gallon	Fair	Not sampled	Partial
D-114	Bld-3 (227 S. St Claire)	Main Floor	Steel Container	Open Top	5-gallon	Fair	Not sampled	Partial
D-115	Bld-3 (227 S. St Claire)	Main Floor	Steel Container	Open Top	5-gallon	Fair	Not sampled	Partial
D-116	Bld-3 (227 S. St Claire)	Main Floor	Steel Container	Open Top	5-gallon	Fair	Not sampled	Partial
D-117	Bld-3 (227 S. St Claire)	Main Floor	Steel Drum	Close Top	55-gallon	Fair	yes Flammable test Positive pH=6 PID Reading - 103 ppm	Partial with "UN 1897" perchloroethylene
D-118	Bld-3 (227 S. St Claire)	Back room	Steel Container	Open Top	5-gallon	Fair	Not sampled	-
D-119	Bld-3 (227 S. St Claire)	Back room	Fiberglass Cylinder	Open Top	5-gallon	Fair	Not sampled	-

Drum Inventory Table  
 Plabell Rubber Manufacturing Plant Site  
 Toledo, Lucas County, Ohio  
 Drum Inventory Sheet  
 September 10-11, 2008

Drum Number	Building	Location in Building	Container/Drum	Type	Size	Condition	Hazcat Drum (pH and/or Flammability) (RESULTS)	Comments
D-120	Bld-3 (227 S. St Claire)	Back room	Fiberglass Cylinder	NA	10-20 gal	Fair	Not sampled	Fiberglass Water softener Tank
D-121	Bld-3 (227 S. St Claire)	Back room	Fiberglass Cylinder	NA	10-20 gal	Fair	Not sampled	Fiberglass Water softener Tank
D-122	Bld-3 (227 S. St Claire)	Back room	Steel Container	Open Top	5-gallon	Fair	Not sampled	Labeled "Thixon" partial volume
D-123	Bld-3 (227 S. St Claire)	Back room	Steel Container	Open Top	5-gallon	Fair	Not sampled	Labeled "Monothane"
D-124	Bld-3 (227 S. St Claire)	Back room	Poly Container	Close Top	5-gallon	Fair	Not sampled	-
D-125	Bld-3 (227 S. St Claire)	Back room	Steel Container	Open Top	5-gallon	Fair	Not sampled	-
D-126	Bld-3 (227 S. St Claire)	Back room	Poly Container	Open Top	5-gallon	Fair	Not sampled	-
D-127	Bld-3 (227 S. St Claire)	Back room	Steel Container	Open Top	5-gallon	Fair	Not sampled	Labeled "Thixon" partial volume
D-128	Bld-3 (227 S. St Claire)	Back room	Steel Container	Open Top	10-gallon	Fair	Not sampled	Grease Material
D-129	Bld-3 (227 S. St Claire)	Back room	Poly Container	Open Top	5-gallon	Fair	Not sampled	"Ferro Corp Polymer Additive Synpro"
D-130	Bld-1 (330 S St Claire)	Loading area	Steel Container	Close Top	2-gallon	Fair	Not sampled	Marked as "Flexane 80 liquid"
Tank UST	Near Building 2	Outside	UST		Unknown	Unknown	Yes Non Flammable	Volume unknown
D-Building 3	Bld-3 (227 S. St Claire)	throughout Building	Assorted 1-gallon or less	assorted	1 gallon or less	poor to fair	Not sampled	Assorted 1 gallon (2) and 1-qt containers (7)