

# Mitcham Street Drum Removal Daily Progress Report 20 November 2009

## 1. Dynamac Corporation (START-3):

EPA Contract No.	EP-W-06-077
TDD No.	TO-0001-09-09-01
Project Location	Malakoff, Henderson County, Tx
Work Activity	Removal Assessment
EPA On-scene Coordinator	Mike McAteer
Dynamac Project Manager	Jeff McCully

## 2. Mitcham Street Drum Removal Site Personnel:

- A. Federal Oversight Provided By: Mike McAteer, EPA OSC
- B. START-3 Team Leader: Chantelle Billiot  
Total Number of START-3 Personnel On-Site: 1 (Dynamac)
  
- C. ERRS Team Leader: N/A  
Total Number of ERRS Personnel On-Site: 4 (EQM)  
1 Site Security personnel contracted by ERRS

## 3. Mitcham Street Site Conditions:

- A. Weather: N/A

## 4. Mitcham Street Site Activities:

### A. START-3 Activities

- a. Site Progress Made: START-3 continues to compile analytical data. START-3 conducted periodic air monitoring while demolition activities were occurring.
- b. Problems Encountered: None
- c. Anticipated Problems/Recommended : None
- d. Health and Safety Problems/Recommended Solutions: None

### B. ERRS Activities

- a. Site Progress Made: Building demolition has been completed. A second excavator was delivered with a hammer to assist with breakup of the concrete pad. ERRS continues to separate tin and steel into roll-offs.
- b. Problems Encountered: None
- c. Anticipated Problems/Recommended Solutions: None
- d. Health and Safety Problems/Recommended Solutions: None

## 5. Future Activities:

- A. START-3 will continue compiling analytical data into a spreadsheet for EPA and work on generating a map of soil excavation areas. START-3 will continue periodic air monitoring.
- B. ERRS will continue with demolition of concrete flooring and continue separation of tin and steel. When complete, excavation of contaminated soil will begin.

## **ATTACHMENTS**

Site Photographs



Breaking up concrete pad



Discolored liquid under concrete pad



Discolored concrete