

**United States Environmental Protection Agency
Region IV
POLLUTION REPORT**

Date: Friday, February 4, 2005

From: Richard Jardine

Subject: First and Final POLREP

Denbury Resources ZR Umbarger Tank Battery

South Poplar Street, Heidelberg, MS

Latitude: 31.8782500

Longitude: -88.9932600

POLREP No.:	1	Site #:	
Reporting Period:		D.O. #:	
Start Date:	1/30/2005	Response Authority:	OPA
Mob Date:	2/1/2005	Response Type:	Emergency
Demob Date:	2/2/2005	NPL Status:	Non NPL
Completion Date:		Incident Category:	Removal Action
CERCLIS ID #:		Contract #	
RCRIS ID #:		Reimbursable Account #	
FPN#			

Site Description

On 30JAN05 a bleed-off line was left on filling and overflowing a sump with an estimated 15 barrels of crude oil from the storage system at the ZR Umbarger Tank Battery in Heidelberg, MS. This facility is operated by Denbury Resources.

Current Activities

Denbury personnel and contract support initiated response activities including recovery of pooled oil with a vacuum truck, excavating saturated soil with an excavator, applying absorbent materials to spilled crude, and establishing a containment pond to capture/filter stormwater runoff. Mississippi DEQ and EPA conducted oversight of emergency response activity.

Planned Removal Actions

The facility intends to continue containment measures and properly treat/dispose saturated soil.

Next Steps

Mississippi DEQ will oversight completion of response measures.

Key Issues

Facility conducted appropriate response actions; however, heavy rains caused some oil to escape containment and enter waters of the United States.

response.epa.gov/DenburyZRUmbargerTankBattery