

U.S. ENVIRONMENTAL PROTECTION AGENCY  
POLLUTION/SITUATION REPORT  
19 Park Street Residence - Removal Polrep  
Initial Removal Polrep



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY  
Region II

**Subject:** POLREP #1  
Initial POLREP  
19 Park Street Residence  
A25W  
Ellenville, NY

**To:** Andrew Raddant, Department of Interior  
Frank Csulak, National Oceanic & Atmospheric Administration  
Dennis Farrar, NYSDEC  
Bob Marino, NYSDEC  
Eric Mosher, USEPA, Region 2, ERRD-RPB  
Tim Grier, USEPA Headquarters 5202G  
Ellen Banner, USEPA Region 02  
Joe Rotola, USEPA Region 02  
George Zachos, USEPA Region 2 ERRD  
Beckett Grealish, USEPA Region 2, ERRD, RAB  
James Daloia, USEPA, Region 2, ERRD-RPB  
Mary Mears, USEPA, Region 2, PAD  
Gary Bowitch, Bowitch and Coffey  
Amanda LaValle, Ulster County  
Karla Guerrero, Weston Solutions

**From:** Paul L. Kahn, OSC

**Date:** 9/25/2015

**Reporting Period:**

**1. Introduction**

**1.1 Background**

<b>Site Number:</b>	A25W	<b>Contract Number:</b>	EP-S2-15-02
<b>D.O. Number:</b>		<b>Action Memo Date:</b>	
<b>Response Authority:</b>	CERCLA	<b>Response Type:</b>	Emergency
<b>Response Lead:</b>	EPA	<b>Incident Category:</b>	Removal Action
<b>NPL Status:</b>	Non NPL	<b>Operable Unit:</b>	
<b>Mobilization Date:</b>	9/29/2015	<b>Start Date:</b>	9/24/2015
<b>Demob Date:</b>		<b>Completion Date:</b>	
<b>CERCLIS ID:</b>	NYN000202262	<b>RCRIS ID:</b>	
<b>ERNS No.:</b>	304844	<b>State Notification:</b>	
<b>FPN#:</b>		<b>Reimbursable Account #:</b>	

**1.1.1 Incident Category**

Emergency Response for abandoned drums in a residential neighborhood.

**1.1.2 Site Description**

Two 35-gallon drums abandoned in the rear of a vacant residence.

**1.1.2.1 Location**

The site is in a residential area of closely situated houses.

**1.1.2.2 Description of Threat**

Drum of waste oil and drum of waste paint abandoned in an open rear yard that is accessible to trespassers and vandals.

**1.1.3 Preliminary Removal Assessment/Removal Site Inspection Results**

OSC accessed the site on 9/16/2015 and visually identified a drum of waste oil and a drum of waste paint.

## 2. Current Activities

### 2.1 Operations Section

#### 2.1.1 Narrative

#### 2.1.2 Response Actions to Date

#### 2.1.3 Enforcement Activities, Identity of Potentially Responsible Parties (PRPs)

The potentially responsible party identified to date is the current property owner, Robert J. Stewart.

#### 2.1.4 Progress Metrics

<i>Waste Stream</i>	<i>Medium</i>	<i>Quantity</i>	<i>Manifest #</i>	<i>Treatment</i>	<i>Disposal</i>
waste oil	liquid	35 gals			
waste paint	liquid	35 gals			

### 2.2 Planning Section

#### 2.2.1 Anticipated Activities

Mobilize cleanup contractor to the site, overpack drums and relocate them to a temporary secure local location.

#### 2.2.1.1 Planned Response Activities

Dispose of the two drums, preferably via merging into the local HHW staging area or via traditional commercial disposal.

#### 2.2.1.2 Next Steps

See above.

#### 2.2.2 Issues

None.

### 2.3 Logistics Section

No information available at this time.

### 2.4 Finance Section

#### Estimated Costs \*

	<b>Budgeted</b>	<b>Total To Date</b>	<b>Remaining</b>	<b>% Remaining</b>
<b>Extramural Costs</b>				
ERRS - Cleanup Contractor	\$10,000.00	\$0.00	\$10,000.00	100.00%
TAT/START	\$2,000.00	\$0.00	\$2,000.00	100.00%
<b>Intramural Costs</b>				
USEPA - Direct	\$2,000.00	\$0.00	\$2,000.00	100.00%
<b>Total Site Costs</b>				
	\$14,000.00	\$0.00	\$14,000.00	100.00%

\* The above accounting of expenditures is an estimate based on figures known to the OSC at the time this report was written. The OSC does not necessarily receive specific figures on final payments made to any contractor(s). Other financial data which the OSC must rely upon may not be entirely up-to-date. The cost accounting provided in this report does not necessarily represent an exact monetary figure which the government may include in any claim for cost recovery.

### 2.5 Other Command Staff

No information available at this time.

**3. Participating Entities**

**3.1 Unified Command**

**3.2 Cooperating Agencies**

**Ulster County**

**Village of Ellenville**

**4. Personnel On Site**

No information available at this time.

**5. Definition of Terms**

No information available at this time.

**6. Additional sources of information**

No information available at this time.

**7. Situational Reference Materials**

No information available at this time.

POLREP #1 Last Updated 9/25/2015