

U.S. ENVIRONMENTAL PROTECTION AGENCY
POLLUTION/SITUATION REPORT
Wade Road Oil Spill - Removal Polrep
Initial Removal Polrep



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
Region V

Subject: POLREP #1
Initial
Wade Road Oil Spill

Owosso, MI
Latitude: 43.0287368 Longitude: -84.2596776

To:

From: Jeff Lippert/Kim Churchill, On-Scene Coordinator

Date: 11/27/2015

Reporting Period: 11/26/2015-11/27/2015

1. Introduction

1.1 Background

Site Number:	Contract Number:
D.O. Number:	Action Memo Date:
Response Authority: OPA	Response Type: Emergency
Response Lead: EPA	Incident Category: Removal Action
NPL Status: Non NPL	Operable Unit:
Mobilization Date: 11/26/2015	Start Date: 11/26/2015
Demob Date:	Completion Date:
CERCLIS ID:	RCRIS ID:
ERNS No.:	State Notification:
FPN#: E16504	Reimbursable Account #:

1.1.1 Incident Category

Emergency Response

1.1.2 Site Description

County Drain in rural/agricultural setting.

1.1.2.1 Location

1999 North Wade Road, Owosso, MI

1.1.2.2 Description of Threat

Oil in County Drain threatening Shiawassee River.

1.1.3 Preliminary Removal Assessment/Removal Site Inspection Results

EPA arrived on scene at 2230 hrs on 11/26/2015 and observed oil in County Drain.

2. Current Activities

2.1 Operations Section

2.1.1 Narrative

EPA mobilized to the site and observed oil in the County Drain within a collection point at a culvert near the intersection of Wade Road and Wilkinson Road that was established by the Shiawassee County EM.

2.1.2 Response Actions to Date

11/26/2015-11/27/2015: EPA deployed absorbent boom within the County Drain to create collection points near the intersection of Wade Road and Wilkinson Road. Absorbent pads were used to remove oil from the collection points. Oiled pads and boom were bagged for disposal. A fingerprint sample was collected for analysis at the USCG laboratory. At 0400 hrs on 11/27/2015 EPA left site and returned at 1000 hrs on 11/27/2015 to further assess the situation with Shiawassee County EM and MDEQ in daylight hours.

During the daylight assessment, EPA observed pockets of oil, oiled vegetation, and sheen for approximately one mile upstream of the collection point. Three dead Canada geese were also observed. EPA mobilized additional resources and issued a notice of federal interest to the property owner, Mr. George Zmitko Jr.

2.1.3 Enforcement Activities, Identity of Potentially Responsible Parties (PRPs)

The oil appears to be emanating from a drainage tile located at 5150 W. Mason, Owosso, MI. A team will be assembled to pursue enforcement activities.

2.1.4 Progress Metrics

<i>Waste Stream</i>	<i>Medium</i>	<i>Quantity</i>	<i>Manifest #</i>	<i>Treatment</i>	<i>Disposal</i>

2.2 Planning Section

2.2.1 Anticipated Activities

Continue to collect and remove oil from County Drain.

Dispose of oily waste.

Continue to pursue enforcement.

2.2.1.1 Planned Response Activities

Continue to collect and remove oil from County Drain.

Dispose of oily waste.

2.2.1.2 Next Steps

Continue to collect and remove oil from County Drain.

Dispose of oily waste.

Continue to pursue enforcement.

2.2.2 Issues

High potential for heavy rain in the forecast.

2.3 Logistics Section

N/A

2.4 Finance Section

No information available at this time.

2.5 Other Command Staff

2.5.1 Safety Officer

The OSC is fulfilling the role of Safety Officer.

2.5.2 Liaison Officer

The OSC is fulfilling the role of Liaison Officer.

2.5.3 Information Officer

The OSC is fulfilling the role of Information Officer.

3. Participating Entities

3.1 Unified Command

N/A

3.2 Cooperating Agencies

MDEQ
Shiawassee County EM

4. Personnel On Site

EPA: 2
START: 1
ERRS: 4
MDEQ: 1
Shiawassee County: 1

5. Definition of Terms

EPA - United States Environmental Protection Agency
EM - Emergency Management
ERRS - Emergency Rapid Response Service
FPN - Federal Pollution Number
MDEQ - Michigan Department of Environmental Quality
NCP - National Oil and Hazardous Substances Pollution Contingency Plan
NRC - National Response Center
OPA - Oil Pollution Act of 1990
OSC - On-Scene Coordinator
PolRep - Pollution Report
RP - Responsible Party
START - Superfund Technical Assessment and Response Team

6. Additional sources of information

6.1 Internet location of additional information/report

www.epaosc.org/waderoad

6.2 Reporting Schedule

Additional PolReps will be provided as needed.

7. Situational Reference Materials

OPA

NCP