# U.S. ENVIRONMENTAL PROTECTION AGENCY POLLUTION/SITUATION REPORT

Pirch Way Oil Spill - Combs Property - Removal Polrep Final Removal Polrep



# UNITED STATES ENVIRONMENTAL PROTECTION AGENCY Region III

Subject: POLREP #4

Cleanup completed - Final Polrep Pirch Way Oil Spill - Combs Property

Elkridge, MD

Latitude: 39.1881900 Longitude: -76.7884629

To:

From: Gregory Ham, On Scene Coordinator

**Date:** 4/26/2016 **Reporting Period:** 04/26/2016

#### 1. Introduction

#### 1.1 Background

Site Number: Z3NG Contract Number: D.O. Number: Action Memo Date:

 Response Authority:
 OPA
 Response Type:
 Emergency

 Response Lead:
 EPA
 Incident Category:
 Removal Action

NPL Status: Non NPL Operable Unit:

 Mobilization Date:
 1/7/2016
 Start Date:
 1/7/2016

 Demob Date:
 4/25/2016
 Completion Date:
 4/25/2016

CERCLIS ID: RCRIS ID:

ERNS No.: State Notification:

FPN#: E16305 Reimbursable Account #:

## 1.1.1 Incident Category

Removal action at an oil spill

## 1.1.2 Site Description

Oil spill at a residential property.

## 1.1.2.1 Location

6628 Pirch Way, Elkridge, Maryland

#### 1.1.2.2 Description of Threat

Approximately 110 gallons of home heating oil spilled from an outdoor storage tank that had fallen over. The oil migrated approximately 100 feet downgradient, and was moving towards a storm drain that lead to a navigable waterway. Based on the foregoing, the OSC determined that this incident posed a substantial threat of discharge of crude oil into the navigable waters of the U.S.

## 1.1.3 Preliminary Removal Assessment/Removal Site Inspection Results

See previous Polreps.

## 2. Current Activities

## 2.1 Operations Section

# 2.1.1 Narrative

On April 25, 2016, the OSC and the EPA contractor returned to the site and placed additional topsoil on the excavation area, applied grass seed, and placed erosion matting over the seeded area.

#### 2.1.2 Response Actions to Date

# 2.1.3 Enforcement Activities, Identity of Potentially Responsible Parties (PRPs)

## 2.1.4 Progress Metrics

Waste Stream	Medium	Quantity	Manifest #	Treatment	Disposal

# 2.2 Planning Section

## 2.2.1 Anticipated Activities

No further actions are planned for this site.

## 2.2.1.1 Planned Response Activitie

## 2.2.1.2 Next Steps

Closeout of site.

**2.2.2 Issues** 

#### 2.3 Logistics Section

No information available at this time.

#### 2.4 Finance Section

No information available at this time.

#### 2.5 Other Command Staff

No information available at this time.

#### 3. Participating Entities

No information available at this time.

## 4. Personnel On Site

On April 25, 2016 an OSC and three contractor personnel were onsite to complete site restoration.

#### 5. Definition of Terms

No information available at this time.

## 6. Additional sources of information

6.1 Internet location of additional information/report www.epaosc.org/PirchWay

6.2 Reporting Schedule

# 7. Situational Reference Materials

No information available at this time.