

United States Environmental Protection Agency
Region IV
POLLUTION REPORT

Date: Tuesday, May 22, 2007

From: Jose Negron

Subject: Continuation of Removal Actions
Cannon Road Drum Site
148 Cannon Road, Social Circle, GA
Latitude: 33.6525200
Longitude: -83.7206200

POLREP No.:	9	Site #:	A4PM
Reporting Period:	5/2202007- 5/25/2007	D.O. #:	0053
Start Date:	1/16/2007	Response Authority:	CERCLA
Mob Date:	1/16/2007	Response Type:	Time-Critical
Demob Date:		NPL Status:	Non NPL
Completion Date:		Incident Category:	Removal Action
CERCLIS ID #:	GAN000409893	Contract #	
RCRIS ID #:			

Site Description

The Cannon Road Drum Site (formerly Social Circle Cotton Mill) is located at 148 Cannon Road in the city of Social Circle in Walton County, Georgia. The site coordinates, as measured from the front entrance to the property, is N 33.65252 Latitude by W 83.72062 Longitude. The site is bordered on the south and west by residential homes and on the north and east by a railroad and an overgrown field, respectively. Many of the old mill houses along the western and southern sides of the site are still occupied.

The Social Circle Cotton Mill operated at the site from 1901 until 1982. The mill manufactured bed sheeting made from 35% cotton and 65% polyester. During its peak the mill employed 225 workers. In April 1994, the mill's main structure was severely damaged by fire. Less than half of the 3-story brick structure remains standing today. There are also several support buildings for the mill in varying stages of decay on the 3.84-acre site.

The site was referred to EPA by the city of Social Circle. Records indicate the property has been leased for various types of business use. The most recent tenant used the property to store several thousand containers of mixed hazardous substances. The bulk of the materials appears to have been procured from Department of Defense surplus. In 1997, the containers were abandoned at the site when business operations ceased at the property.

The abandoned substances include resins, adhesives, mercury amalgam, cleaning solvents, paint thinners and some unknowns. Incompatible containers of hazardous substances are commingled together and vary in size, type and degree of degradation. Evidence of vagrant trespass and vandalism was observed during EPA's December 2006 reconnaissance of the site.

Current Activities

ERSS personnel move back to site to initiate transportation and disposal activities.

Planned Removal Actions

Inform City of Social Circle and other interested parties of potential completion date.

Next Steps

Develop demobilization plan

Key Issues

NONE

response.epa.gov/cannonroaddrum