

**United States Environmental Protection Agency  
Region IV  
POLLUTION REPORT**

**Date:** Monday, October 1, 2007

**From:** James Webster

**Subject:** Interim Report

Circle Environmental #2

2222 Albany Hwy, Dawson, GA

Latitude: 31.7611000

Longitude: -84.4361000

<b>POLREP No.:</b>	3	<b>Site #:</b>	A4FRD
<b>Reporting Period:</b>	24SEP07 to 0OCT07	<b>D.O. #:</b>	
<b>Start Date:</b>	9/10/2007	<b>Response Authority:</b>	CERCLA
<b>Mob Date:</b>	9/10/2007	<b>Response Type:</b>	Emergency
<b>Demob Date:</b>		<b>NPL Status:</b>	Non NPL
<b>Completion Date:</b>		<b>Incident Category:</b>	Removal Action
<b>CERCLIS ID #:</b>	GAN000410082	<b>Contract #</b>	
<b>RCRIS ID #:</b>			

**Site Description**

Activity conducted during this period was to arrange for the safe keeping of the drums off-Site until EPA can arrange for appropriate disposal. EPA also collected soil samples from the area where the drums were discovered as well as from the potential leaks from the non-DOT roll off boxes.

**Current Activities**

There is no Site activity being conducted at present.

**Planned Removal Actions**

EPA is notifying PRPs regarding the status of this site as well as their environmental responsibilities.

**Next Steps**

Arrange for proper disposal of the crushed drums and drums containing shop wastes. Also receive data from the soil sampling to determine whether a soil removal is appropriate.

[response.epa.gov/circleenvironmental2](http://response.epa.gov/circleenvironmental2)